

(NO 11)

CRJ DSP

(ONE)

1968 JUN 8 PM 5-53

);HOLB TURN 728L3CUT  
 );HOLB TURN 728LE1 6 881730WW10286Y818  
 );HOLB TURN 728KCUT

1	ATSF	562WCECREW	10253	25	-1028610253
2	ATSF	48991 AE	10253	25	-1028610253
3	ATSF	184106HCE	10253	25	-1028610253
4	ATSF	80207HC CUT			
4	ATSF	80207HCE	1026CUT		
4	ATSF	80207HCE	10253	26	-1028610253
5		CUT			
5	ATSF	80065HC CUT			
5	ATSF	80065HCE	10253	26	-1028610253
6	ATSF	184288HCE	10253	26	-1028610253
7	ATSF	48343A53	10253APA	32	-1028610253
8	ATSF	49024A53CUT			
8	ATSF	49024A5E	10253APA	CUT	
8	ATSF	49024A5E	10253APA	32	-1028610253
9	ATSF	48367 BE	10253APA	26	-1028610253
10	ATSF	47859 BE	10253APA	26	-1028610253
11	ATSF	47829 BE	10253APA	26	-1028610253
12		ATCUT			
12	UP	165706 BE	10253APA	31	-1028610253
13	TP	121214 BE	10253APA	23	-1028610253
14	IC	144180 BE	10253APA	28CUT	
14	IC	144180 BE	10253APA	28	-1028610253
15	SP	211507 BE	10253APA	28	-1028610253
16	SF	217150 BE	10253APA	30	-1028610253
17	SF	212176 BE	10253APA	28	-1028610253
18	SSW	48443 BE	10253APA	WTCUT	
18	SSW	48443 BE	10253APA	25	-1028610253
19	NP	3997BECUT			
		QOCUT			
19	NP	3997 BE	10253APA	25	-1028610253
20	SP	217158 BE	10253APA	25	-1028610253
21	SP	222442 BE	10253APA	25	-1028610253
22	SP	222438 BE	10253APA	25	-1028610253

(CONTD LL)

(TWO)

);HOLB TURN 728LE1 6 881730WW10286Y818

23	SP	223982	BE	10253APA	25	-1028610253
24	SP	223609	BE	10253APA	25	-1028610253
25	SP	223200	BE	10253APA	30	-1028610253
26	BCUT					
26	GN	36434	BE	10253APA	EQ CUT	
26	GN	36434	BE	10253APA	31	-1028610253
27	WP	35367	BE	10253APA	ECUT	
27	WP	35367	BE	10253APA	31	-1028610253
28	ATSF	47628	BE	10253APA	31	-1028610253
29	ATSF	48035	BE	10253APA	31	-1028610253
30	ATSF	47573	BE	10253APA	31	-1028610253
31	NP	7735	BE	10253APA	28	-1028610253
32	GN	35403	BE	10253APA	29	-1028610253
33	ATSF	49000	BE	CUT		
33	ATSF	49000	BE	10253 CUT		
33	ATSF	49000	BE	10253APA	36	-1028610253
34	ATSF	49220	BE	10253APA	35	-1028610253
35	RA	40038	BE	10253APA	35	-1028610253
36	ATSF	47675	BE	10253APA	35	-1028610253
37	APA	1215GWCCUT				
37	APA	1215GWECHIPS		10253APA	112 80	-1028610253
38	APA	1209GWLCHIPS		10253APA	112 80	-1028610253
(CUT LINE 37 READ AS FOLLOWS)						
37	APA	1215BWCUT				
37	APA	1215GWLCHIPS		10253APA	112 80	-1028610253
38	CUT					
39	APA	1205GWLCHIPS		10253APA	112 80	-1028610253
40	APA	1222GWLCHIPS		10253APA	112 80	-1028610253
41	ATSF	71940GWLCHIPS		10253APA	112 80	-1028610253
42	ATSF	71919GWLCHIPS		10253APA	112 80	-1028610253
43	ATSF	71926GWLCHIPS		10253APA	CUT	
43	ATSF	71926GWLCHIPS		10253APA	112 80	-1028610253

(CONTD LL)

(THREE)

);HOLB TURN 728LE1 6 881730WW10286Y818

44 YQRTRCTUCUT

44 ATSF 61454GWLLBR 10253APA 58 31 -1028610253

45 MP 351127GWLLBR 10253APA 61 32 CUT

45 .CUT

45 MP 351127GWLLBR 10253APA 61 32 -1028610253

46 ATSF 72151GWLCHIPS 10253APA 112 80 -1028610253

47 ATSF 72153GWLCHIPS 10253APA 112 30CUT

47 ATSF 72153GWLCHIPS 10253APA 112 80 -1028610253

48 APA 1405LPLLOGS 10253APA 50CUT

48 APA 1405LPLLOGS 10253 APA 50 20 -12CUT

48 APA 1405LPLLOGS 10253APA 50 20 -1028610253

49 APA 1446LPLLOGS 10253APA 50 20 -1028610253

50 APA 1433LPLLOGS 10253APA 50 20 -1028610253

51 APA 1440LPLLOGS 10253APA 50 20 -1028610253

52 APA 1436LPLLOGS 10253APA 50 20 -1028610253

53 APA 1459LPLLOGS 10253APA 50 20 -01CUT

53 APA 1459LPLLOGS 10253APA 50 20 -1028610253

54 APA 1443LPLLOGS 10253APA 50 20 -1028610253):75

(CTU CUT PRECEDING LINE)

54 APA 1443LPLLOGS 10253APA 50 20 -1028610253

55 ATSF 71905GWLCHIPS 10253APA 50 20 -1028610253

56 ATSF 71952GWLCHIPS 10253APA 50 20CUT

(CUT LINE 55 READ AS FOLLOWS)

55 ATSF 71905GWLCHIPS 10253APA 112 80 -1028610253

56 ATSF 71952GWLCHIPS 10253APA 112 80 -1028610253

57 ATSF 49018B5E 10253APA 29 -1028610253

58 ATSF 47678B5E 10253APA 29 -1028610253

59 ATSF 49747B5E 10253APA 29 -1028610253

60 ATSF 48961B5E 10253APA 29 -1028610253

61 ATSF 49549B5E 10253APA 29 -1028610253

62 UTLX 83524 TLSODA 10253APA 97 65 -1028610253

63 GATX 71455 TLSODA 10253APA 94 64 -1028610253

64 UTLX 63947 TLCUT

64 UTLX 63947 TE 10253APA 30 -1028610253

(END LL CKS 22LDS 41 MTYS 64 CARS 3100 TONS)